

New York City Department of Education Report Pursuant to Local Law 12 of 2015 November 1, 2019

Background

The New York City Department of Education monitors and addresses environmental concerns in or adjacent to NYC school buildings involving groundwater, ambient air, gas, soil, soil gas, and dust which may affect students and staff occupying NYC school buildings.

The following report, as required by Local Law 12 of 2015, contains the results of reportable environmental inspections and environmental reports that took place from July 2018 through June 2019.

Local Law 12 of 2015 specifies that this annual report shall include:

1. A summary of any reportable environmental inspections or environmental reports for the prior school year, including, but not limited to, information regarding any inspection and sampling of groundwater, ambient air, gas, soil, soil gas, and dust, unless such reporting is already required by local law.

See attached report

2. Information regarding any investigative or remedial work conducted by the department, in response to any reportable environmental inspection, to mitigate the effects of any air, soil, water, or indoor environment condition including, but not limited to, measures taken to address the presence of hazardous substances, contaminants and pollutants that exceed maximum levels, the time frame within which such action was taken, the timeframe within which employees and parents of students were notified of such action and information regarding whether such air, soil, water or indoor environment condition was resolved as a result of such action.

See attached report

3. Information regarding any reportable environmental inspection or any environmental report related to the overall progress of the department's efforts to improve air quality in public schools, including any reportable environmental inspection for air quality related to school renovations, including, but not limited to, the replacement of ceilings.

No information to report

4. The current status of any site subject to a consent order or agreement with the United States environmental protection agency, the New York state department of environmental conservation or the New York state department of health.

Marked with an asterisk (*) in attached report, column C "Building Code"



Community School District	Council District	Building Code	DBN	School/Program Name	Date Report Received	Date Communication Sent to Stakeholders	Reportable Incident Type	Action Performed or Will be Performed	Status	SCA Comments
			02M139	Stephen T. Mather Building Arts & Craftsmanship High School						
			84M170	Success Academy Hell's Kitchen (Manhattan 2)			Soil Quality: exceedances for metals and pesticides.			
2	3	M625	02M393	Business Of Sports School	7/11/2018	8/31/2018		Materials excavated and disposed of off-site.	Resolved	
			02M507	Urban Assembly Gateway School for Technology						
			84M523	Success Academy Charter School - Upper West						
31	49	R831	31R074	P.S. 74 Future Leaders Elementary School	7/12/2018	8/31/2018	Soil Quality: exceedances for metals.	Remaining soil covered by concrete surfaces.	Cancelled	Job was cancelled.
10	14	14 X115	10X363	Academy For Personal Leadership And Excellence	7/25/2018	8/31/2018	Soil Vapor: several VOCs exceeded background. Tetrachloroethene (PCE) exceeded the AGV. Soil Quality: exceedances for one VOC, several	The onsite soils are currently covered by either asphalt, concrete pavement, or	Ongoing	Construction has not yet
	10 14				East Fordham Academy for the Arts	,, = 0, = 0 = 0	0,51,2010	SVOCs, metals, pesticides, and one PCB. Groundwater: exceedances for one VOC, several SVOCs, and two metals.	landscaped areas with vegetative cover. Groundwater is not used for drinking.	
6	10	M048	06M048	P.S. 048 P.O. Michael J. Buczek	8/2/2018	10/24/2018	Soil Quality: contaminated by petroleum spill.	Materials excavated and disposed of off-site. Soil not accessible to students. Dust control measures and odor suppressants to prevent potential discomfort.	Resolved	
31	50	R054	31R054	P.S. 054 Charles W. Leng	8/3/2018	8/31/2018	Soil Vapor: several VOCS exceeding background. Soil Quality: exceedances for one VOC, one SVOC, and one pesticide; several metals exceedances.	Remaining soil covered by either asphalt, concrete pavement, or landscaped areas with vegetative cover. Soil to be excavated during construction will be properly tested and appropriately reused or disposed of off-site. Topsoil will be placed over all landscaped areas.	Ongoing	
			84M174	Success Academy Union Square (Manhattan 1)						
			02M374	Gramercy Arts High School						
2	2	M460	02M399	The High School For Language And Diplomacy	8/16/2018	8/31/2018	Sail Quality averagences for two SVOCs	Materials averaged and disposed of off site	Doselved	
2	2	101460	02M438	International High School at Union Square	8/10/2018	8/31/2018	Soil Quality: exceedances for two SVOCs.	Materials excavated and disposed of off-site.	Resolved	
			02M533	Union Square Academy for Health Sciences						
			02M546	Academy for Software Engineering						
18	46	K516	18K566	Brooklyn Generation School	8/16/2018	8/31/2018	Soil Quality: exceedances for SVOCs and metals.	Materials excavated and disposed of off-site.	Resolved	
24	30	Q247	24Q128	P.S. 128 The Lorraine Tuzzo, Juniper Valley Elementary School	8/16/2018	8/31/2018	Soil Quality: exceedances for one SVOC, and several metals and pesticides.	Materials excavated and disposed of off-site.	Resolved	
			75Q255	P.S. Q255			several metals and pesticides.	·		

^{*}Site subject to consent order or agreement with US EPA NYC Department of Education School Operations



Community School District	Council District	Building Code	DBN	School/Program Name	Date Report Received	Date Communication Sent to Stakeholders	Reportable Incident Type	Action Performed or Will be Performed	Status	SCA Comments
10	14	X115	10X363	Academy For Personal Leadership And Excellence	8/20/2018	8/31/2018	Soil Quality: exceedances for two metals.	Materials excavated and disposed of off-site.	Resolved	
10	10X459	10X459	East Fordham Academy for the Arts	0,20,2010	0,31,2010	Son quanty: execedances for two metals.	Waterials executed and disposed of oil site.	Resolved		
11	12	X087	11X087	P.S. 087 Bronx	8/24/2018	8/31/2018	Soil Vapor: several VOCs exceeded background. Soil Quality: exceedances for one VOC, several metals, two pesticides, and PCB. Groundwater: exceedances for one metal.	Onsite soil is currently covered by either asphalt, concrete pavement, or landscaped areas with vegetative cover. Groundwater is not used for drinking. A soil vapor barrier and SSDS will be integrated into new building design. Soil to be excavated during construction will be properly tested and appropriately reused or disposed of off-site. Topsoil will be placed over all landscaped areas.	Ongoing	
		03M241	STEM Institute of Manhattan		9/12/2018	Soil Quality: exceedances for several SVOCs, pesticides, and metals.	Materials excavated and disposed of off-site.	Resolved		
3	9 M113 84M2	84M279	The Opportunity Charter School	8/31/2018						
			84M386	Success Academy Charter School - Harlem 4						
26	23	Q415	26Q415		9/6/2018 9/12/2018	Soil Quality: exceedances for several pesticides	Materials excavated and disposed of off-site.	Resolved		
20	25	Q413	75Q993	P.S. Q993	3/0/2018	3/12/2018	and metals.	Waterials excavated and disposed of on-site.	Resolved	
27	32	Q335	27Q377	P.S. Q233	9/26/2018	10/30/2019	Groundwater Quality: potable water discoloration.	Discoloration attributed to excess sediment in water caused by utility work in adjacent street. Water filter installed at point of entry to building. Filter and associated potable water piping disinfected and tested; in service since January 2019.	Resolved	
			75Q233	P.S. 377			discoloration.			
17	26	K300	17K354	The School of Integrated Learning	10/5/2010	10/10/2010	Soil Quality: exceedances for several pesticides,	Materials accounted and discussed of off site	Danahard	
17	36	K390	84K357	KIPP AMP Charter School	10/5/2018	10/19/2018	metals, and SVOCs.	Materials excavated and disposed of off-site.	Resolved	
6	10	M048	06M048	P.S. 048 P.O. Michael J. Buczek	10/10/2018	10/24/2018	Soil Quality: contaminated by petroleum spill.	Materials excavated and disposed of off-site. Soil not accessible to students. Dust control measures and odor suppressants to prevent potential discomfort.	Resolved	
31	50	R460	31R460	Susan E. Wagner High School	10/12/2018	10/24/2018	Soil Quality: exceedances for one metal and total polychlorinated biphenyls.	Materials excavated and disposed of off-site.	Resolved	
13	35	K874	17K340	I.S. 340	10/17/2018	10/29/2018	Soil Quality: exceedances for three metals and one pesticide.	Materials excavated and disposed of off-site.	Resolved	
10	11	X448	10X340	P.S. 340	10/24/2018	11/5/2018	Soil Quality: exceedances of metals and semi-volatile compounds.	Materials excavated and disposed of off-site.	Resolved	



Community School District	Council District	Building Code	DBN	School/Program Name	Date Report Received	Date Communication Sent to Stakeholders	Reportable Incident Type	Action Performed or Will be Performed	Status	SCA Comments	
			10X268	Kingsbridge International High School							
			10X342	International School for Liberal Arts							
10	11	X430	10X433	High School for Teaching and the Professions	10/24/2018	11/5/2018	Soil Quality: exceedances of metals and semi- volatile compounds.	Materials excavated and disposed of off-site.	Resolved		
			10X442	Celia Cruz Bronx High School of Music, The			·				
			10X549	Discovery High School							
12	17	X006	12X006	P.S. 006 West Farms	10/26/2018	11/5/2018	Soil Quality: exceedances of metals.	Materials excavated and disposed of off-site.	Resolved		
12	17	X006	75X352	The Vida Bogart School for All Children	10/20/2018	11/3/2018	Soil Quality. exceedances of metals.	iviateriais excavateu anu disposeu oi on-site.	Resolved		
31	51	R840	75R037	The David Marquis School of the Arts	10/26/2018	11/5/2018	Soil Quality: exceedances of metals.	Materials excavated and disposed of off-site.	Resolved		
10	14	X347	10X033	P.S. 033 Timothy Dwight	10/29/2018	11/9/2018	Soil Quality: exceedances of metals, SVOCs, and the USEPA hazardous waste threshold for lead.	All hazardous waste removed and transported off-site; remaining excavation near completion.	Ongoing		
20	38	K105	20K105	P.S. 105 The Blythebourne	10/30/2018	11/9/2018	Soil Quality: exceedances of two metals and two pesticides.	Materials excavated and disposed of off-site.	Resolved		
14	34	K018	14K018	P.S. 018 Edward Bush	11/5/2018	11/14/2018	Soil Quality: exceedances of one metal.	Materials excavated and disposed of off-site.	Resolved		
			18K279	P.S. 279 Herman Schreiber	11/20/2018	11/30/2018	Soil Quality: exceedance of the USEPA hazardous	Materials excavated and disposed of off-site.	Resolved		
18	46	K279	84K724	Leadership Prep Canarsie Charter School (Leadership Prep CS 4)			waste threshold for lead.	Remaining soil covered by asphalt and not accessible to students.			
26	19	0041	26Q041	P.S. 041 Crocheron	11/22/2019		Soil Vapor: several VOCs exceeding background	On-site soil is currently covered by either asphalt, concrete pavement, or landscaped areas with vegetative cover. An SSDS and gas vapor barrier will be integrated into the new	O		
20	13	Q041		75Q993	P.S. Q993	11/23/2018 11/30/2019	11/30/2018	Soil Quality: exceedances for four metals.	building design. All excavated soil will be tested and appropriately reused or disposed of off-site. Topsoil will be placed over all landscaped areas.	Ongoing	
22	48	K254	22K254	P.S. 254 Dag Hammarskjold	11/26/2018	12/5/2018	Soil Quality: exceedances of two metals.	Materials excavated and disposed of off-site.	Resolved		
6	10	M048	06M048	P.S. 048 P.O. Michael J. Buczek	11/29/2018	12/7/2018	Soil Quality: exceedances of one polychlorinated biphenyl compound, two SVOCs, and several VOCs.	Materials excavated and disposed of off-site. Remaining soil covered by asphalt.	Resolved		
7	17	X470	07X473	Mott Haven Village Preparatory High School	12/11/2018	12/20/2018	Soil Quality: exceedance for one pesticide.	Materials excavated and disposed of off-site.	Resolved		
,	1/	Λ4/0	07X495	University Heights Secondary School	12/11/2018	12/20/2010	Son Quanty, exceedance for one pesticide.	iviateriais excavateu anu uisposeu oi oii-site.	VESOIVER		
15	39	K834	75K372	P.S. 372 -The Children's School	12/21/2018	1/3/2019	Soil Quality: exceedances of one metal and several SVOCs.	Materials excavated and disposed of off-site.	Resolved		



Community School District	Council District	Building Code	DBN	School/Program Name	Date Report Received	Date Communication Sent to Stakeholders	Reportable Incident Type	Action Performed or Will be Performed	Status	SCA Comments			
31	51	R005	31R005	P.S. 005 Huguenot	12/24/2018	1/3/2019	Soil Vapor: several VOCs exceeding background. Soil Quality: exceedance of one metal. Groundwater Quality: one volatile, one semi- volatile, and one metal above groundwater standards.	On-site soil covered by either asphalt, concrete pavement or landscaped areas with vegetative cover and inaccessible to students. Groundwater is not used for drinking water. Soil vapor barrier integrated into new building design. Soil excavated during construction will be tested and appropriately reused or disposed of off-site. Topsoil will be placed over all landscaped areas.	Ongoing				
26	23	Q667	75Q004	P.S. Q004	12/26/2018	1/8/2019	Soil Quality: exceedances of several metals and SVOCs.	Materials excavated and disposed of off-site.	Resolved				
28	29	Q003	28Q303	The Academy for Excellence through the Arts	12/27/2018	1/8/2019	Soil Quality: exceedances of one metal and several pesticides.	Materials excavated and disposed of off-site.	Resolved				
2	3 6 M075*			03M075 P.S. 075 Emily Dickinson	1/8/2019 1/11/2019	Spill Investigation: small amount of residual fuel oil remaining in groundwater following closure	Removal of as much of the residual fuel oil in the monitoring wells as feasible over a 6-month period, followed by monitoring for product in each of the wells. Future	Ongoing	Request for spill closure will be submitted to NYSDEC				
3		IVIU75 ·	03M250	M.S. 250 West Side Collaborative Middle School	1/8/2019	1/11/2019	and removal of underground petroleum storage tanks.	monitoring and further remedial efforts will be dictated and overseen by NYSDEC until spill closure can be achieved.	Ongoing	shortly. Spill investigation under NYSDEC oversight.			
9	15	X163	09X163	P.S. 163 Arthur A. Schomburg	1/11/2019	1/24/2019	Soil Vapor: several VOCs exceeding background and tetrachloroethene (PCE) marginally exceeding the AGV. Soil Quality: exceedance of SVOCs and two pesticides.	On-site soils covered by either asphalt, concrete pavement, or landscaped areas with vegetative cover and inaccessible to students. Soil vapor barrier integrated into new building design. Soil excavated during construction will be tested and appropriately reused or disposed of off-site. Topsoil will be placed over all landscaped areas.	Ongoing	An SSDS will also be integrated into the new building.			
			12X531	Archer Elementary School									
12	12 18 X1	X102	12X536	P.S. 536	1/16/2019	1/28/2019	Soil Quality: exceedances of several SVOCs.	Materials excavated and disposed of off-site.	Resolved				
			12X691	Bronx Little School									
3	7	M145	03M145	P.S. 145, The Bloomingdale School	1/28/2019	2/7/2019	Spill Response: release of No. 2 oil from the fuel line of a temporary boiler located in adjacent	Access to the spill area was restricted and made inaccessible to the public and students. Petroleum-impacted materials were	Resolved				
	, 10114.	2.3				03M421	West Prep Academy			roadbed.	containerized and disposed of appropriately.		



Community School District	Council District	Building Code	DBN	School/Program Name	Date Report Received	Date Communication Sent to Stakeholders	Reportable Incident Type	Action Performed or Will be Performed	Status	SCA Comments
6	7	M192*	06M192 P.S. 192 Jacob H. Schiff	1/31/2019		Petroleum Spill: petroleum product was	Recovered product was removed with a vacuum truck and transported off-site to a disposal facility. Monitoring and removal activities will continue to be coordinated with	Ongoing	Annual progress reports associated with an open petroleum spill are submitted to NYSDEC. The 2018 annual report submitted to NYSDEC and	
			06M209	Hamilton Grange Middle School			in the boiler room of the building.	the school custodian until termination is approved by the NYSDEC.		DOE on 1/30/19. The 2019 annual report will be submitted to NYSDEC in January 2020.
20	43	K490	20K490	Fort Hamilton High School	2/28/2019	3/8/2019	Soil Quality: exceedances of two metals and two semi-volatile organic compounds.	Materials excavated and disposed of off-site.	Resolved	
26	23	Q046	26Q046	P.S. 046 Alley Pond	3/5/2019	3/14/2019	Soil Vapor: three VOCs slightly exceeding the NYSDH range of published background concentrations in one soil vapor.	Soil vapor barrier integrated into new building design.	Ongoing	
			17K524	K524 International High School at Prospect Heights			Soil Quality: exceedance for four pesticides and one metal.			
			17K528	The High School for Global Citizenship		- 4: - 4				
17	35	K440	17K547	Brooklyn Academy of Science and the Environment	3/6/2019	3/14/2019		Materials excavated and disposed of off-site.	Resolved	
			17K548	Brooklyn School for Music & Theatre						
			20K503	P.S. 503: The School of Discovery	- I= I= : -	2/44/2242	Soil Quality: exceedance for three metals.	Materials excavated and disposed of off-site.		
20	38	K314	20K506	P.S. 506: The School of Journalism & Technology	3/7/2019	3/14/2019			Resolved	
9	16	X002	09X250	Eximius College Preparatory Academy: A College Board School	3/15/2019	4/3/2019	Soil Quality: exceedance for three metals.	Materials excavated and disposed of off-site.	Resolved	
			09X260	Bronx Center for Science and Mathematics			·			
12	18	12X19	12X195	P.S. 195	3/18/2019	9 4/3/2019	Soil Vapor: one VOC exceeding background concentration.	On-site soils covered by either asphalt, concrete pavement, or landscaped areas with vegetative cover and inaccessible to students. Groundwater not used for drinking water. Soil vapor barrier integrated into new building design. Soil excavated during construction will be tested and appropriately reused or disposed of off-site. Topsoil will be placed over all landscaped areas.	Ongoing	
			12X196 P.S. 196	P.S. 196	3, 20, 2023		Soil Quality: exceedances for metals. Groundwater: exceedances for four SVOCs.		3636	
15	39	K058	15K058	P.S. 058 The Carroll	3/26/2019	4/4/2019	Soil Quality: exceedance for two metals.	Materials excavated and disposed of off-site.	Resolved	



Community School District	Council District	Building Code	DBN	School/Program Name	Date Report Received	Date Communication Sent to Stakeholders	Reportable Incident Type	Action Performed or Will be Performed	Status	SCA Comments
			19K502	FDNY - Captain Vernon A. Richard High School for Fire and Life Safety					Resolved	
19	42	K425	19K507	Performing Arts and Technology High School	2/20/2010	4/4/2010		Nashariala avezantad and disposad of off site		
19	42	K435	19K504	High School for Civil Rights	3/28/2019	4/4/2019	Soil Quality: exceedances for one SVOC.	Materials excavated and disposed of off-site.		
			19K510	World Academy for Total Community Health High School						
4	8	M108	04M108	P.S. 108 Assemblyman Angelo Del Toro Educational Complex	4/9/2019	4/30/2019	Soil Quality: exceedance for one metal.	Materials excavated and disposed of off-site.	Resolved	
30	22	Q085	30Q085	P.S. 085 Judge Charles Vallone	4/10/2019	4/30/2019	Soil Vapor: several petroleum and chlorinated solvent-related VOCs above background. Soil Quality: exceedances for one VOC, several SVOCs, and two metals. Groundwater: exceedances for four SVOCs.	On-site soils covered by either asphalt, concrete pavement, or landscaped areas with vegetative cover and inaccessible to students. Groundwater not used for drinking water. Soil vapor barrier integrated into new building design. Soil excavated during construction will be tested and appropriately reused or disposed of off-site. Topsoil will be placed over all landscaped areas.	Ongoing	
8	18	X138	08X138	P.S. 138 Samuel Randall	5/23/2019	6/12/2019	Soil Vapor: VOCs exceeding background concentration. Soil Quality: exceedances for two metals.	On-site soils covered by either asphalt, concrete pavement, or landscaped areas with vegetative cover and inaccessible to students. Soil vapor barrier integrated into new building design. Soil excavated during construction will be tested and appropriately reused or disposed of off-site. Topsoil will be placed over all landscaped areas.	Ongoing	
11	13	X108	11X108	P.S. 108 Philip J. Abinanti	5/23/2019	6/12/2019	Soil Vapor: VOCs exceeding background concentration. Soil Quality: exceedances for four metals.	On-site soils covered by either asphalt, concrete pavement, or landscaped areas with vegetative cover and inaccessible to students. Soil vapor barrier integrated into new building design. Soil excavated during construction will be tested and appropriately reused or disposed of off-site. Topsoil will be placed over all landscaped areas.	Ongoing	
			75K373	P.S. 373 - Brooklyn Transition Center						
13	36	K458	84K517	Leadership Prep Bedford Stuyvesant Uncommon Prep Charter School	6/17/2019	9/9/2019	Soil Quality: exceedances for mercury and SVOCs.	Materials excavated and disposed of off-site.	Resolved	
			13K553	Brooklyn Academy High School	- 0/1//2019					
		84K780	Brooklyn East Collegiate Charter School							



Community School District	Council District	Building Code	DBN	School/Program Name	Date Report Received	Date Communication Sent to Stakeholders	Reportable Incident Type	Action Performed or Will be Performed	Status	SCA Comments
5	9	M010*	05M499	Frederick Douglass Academy	11/2/2017	11/9/2017	Remediation progress reporting associated with a petroleum spill.	Impacted soil excavated and disposed of off- site. Dust control measures and odor suppressants to prevent potential discomfort.	Resolved	Remediation complete and NYSDEC Spill No. 1608021 closed on 10/9/18.
10	11	X024*	10X024	P.S. 024 Spuyten Duyvil	N/A	N/A	NYSDEC spill remediation.	Small amount of residual fuel oil impacted soil identified below fill ports in sidewalk. Soil excavated summer of 2019.	Ongoing	Request for spill closure submitted to NYSDEC 10/24/19. Spill investigation under NYSDEC oversight.
	22 48 K014*		22K014	J.H.S. 014 Shell Bank				Small amount of residual fuel oil impacted soil identified below fill ports in sidewalk. Soil excavated summer of 2019.	Ongoing	Request for spill closure will be submitted to NYSDEC shortly. Spill investigation under NYSDEC oversight.
22		K014*	75K771	P.S. K771	N/A	·	NYSDEC spill remediation.			
			75K811	P.S. K811 Connie Lekas School						
		K500*	18K617	High School for Innovation in Advertising and Media			I/A NYSDEC spill remediation.	Fuel oil leak from temporary boiler trailer; area cleaned and contained. Small amount of residual fuel oil impacted soil may exist under trailer. Soil will be excavated when boiler trailer is removed from site and request for	Ongoing	Spill investigation under NYSDEC oversight.
18	46		18K633	High School for Medical Professions	N/A					
10	10	11300	18K642	Urban Action Academy	1,47.					
			75K753	P.S. K753 - School for Career Development				spill closure will be submitted to NYSDEC.		
11	15	X096*	11X096	P.S. 096 Richard Rodgers	N/A	N/A	NYSDEC Brownfield Cleanup Program site.	Annual vapor intrusion monitoring conducted in the original school building. SSDS and vapor barrier installed and operational for the addition. Subsurface remedial actions implemented. Groundwater inaccessible and use is prohibited.	Ongoing	Remediation is being performed under NYSDEC BCP.